

1/64	→ .015625	.515625	→ 33/64
1/32	→ .03125	.53125	→ 17/32
3/64	→ .046875	.546875	→ 35/64
1/16	→ .0625	.5625	→ 9/16
5/64	→ .078125	.578125	→ 37/64
3/32	→ .09375	.59375	→ 19/32
7/64	→ .109375	.609375	→ 39/64
1/8	.125	.625	5/8
9/64	→ .140625	.640625	→ 41/64
5/32	→ .15625	.65625	→ 21/32
11/64	→ .171875	.671875	→ 43/64
3/16	→ .1875	.6875	→ 11/16
13/64	→ .203125	.703125	→ 45/64
7/32	→ .21875	.71875	→ 23/32
15/64	→ .234375	.734375	→ 47/64
1/4	.25	.75	3/4
17/64	→ .265625	.765625	→ 49/64
9/32	→ .28125	.78125	→ 25/32
19/64	→ .296875	.796875	→ 51/64
5/16	→ .3125	.8125	→ 13/16
21/64	→ .328125	.828125	→ 53/64
11/32	→ .34375	.84375	→ 27/32
23/64	→ .359375	.859375	→ 55/64
3/8	.375	.875	7/8
25/64	→ .390625	.890625	→ 57/64
13/32	→ .40625	.90625	→ 29/32
27/64	→ .421875	.921875	→ 59/64
7/16	→ .4375	.9375	→ 15/16
29/64	→ .453125	.953125	→ 61/64
15/32	→ .46875	.96875	→ 31/32
31/64	→ .484375	.984375	→ 63/64
1/2	.5	1	1/1